

Work Order ID 149391

149391

AMOD
DG

Page 1

July 22, 2016 3:10:24 PM

Item ID: D3562-041

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Step Weldment

Start Date: 9/22/2016 Start Qty: 4.00

4

Cust Item ID:

Required Date: 9/30/2016 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals:

Process Plan:

SW

Date:

7/25/16

Tooling:

Date:

Run

Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D3562

G

100

0.00

100

Large Fab

Large Fab

Memo

0.44

Large Fab

1-Cut D2622 extrusion as per Dwg D3562
2-Deburr and bevel ends for welding

4 16-11-2

110

QC6- Inspect dimensions to drawing

0.00

110

QC

Memo

0.00

Quality Control

4 NOV 03 2016 DAS 24 9-89

120

Chemical Conversion Coat per QSI005 4.1

0.00

120

HandFinish

Memo

0.09

Hand Finishing

(K4) 2016/11/03 BEB

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Work Order ID 149391

July 22, 2016 3:10:24 PM

149391

Page 2

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Step Weldment
 Start Date: 9/22/2016 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 9/30/2016 Req'd Qty: 4.00 ***4*** Customer:
 Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	QC7-Inspect Chemical Conversion Coat	0.00							
130						4x		DAS 24 9-89	NOV 08 2016
QC	Memo	0.01							
Quality Control									
140		0.00							
140	Small Fab					4x		DAS 43 9-89	NOV 08 2016
Small Fab	Memo	0.89							
Small Fab	1- Transfer drill Rivet holes as per dwg D3562.								
	2-Touch-up rivet holes with alodine as per dwg d3562								
	3-Rivet legs using Scotch-Weld as per dwg D3562.								
	*****Ensure to wipe off any excess magnobond *****								
	A/R Scotch-Weld DP460								
	Batch: 4135579								
	EXP DATE: 9/17								

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By					
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :						
Misidentified	☐	Past Due	☐							

Work Order ID 149391

July 22, 2016 3:10:24 PM

149391

Page 3

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
 Revision ID: Stop ***NS2***
 Item Name: Step Weldment
 Start Date: 9/22/2016 Start Qty: 4.00 ***4*** Cust Item ID:
 Required Date: 9/30/2016 Req'd Qty: 4.00 ***4*** Customer:
 Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
 QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
150	QC5- Inspect part completeness to step on W/O	0.00							
150						<u>4</u>	<u>9102</u>	<u>8 0</u>	<u>AON</u>
QC	Memo	0.01							DAS 24 9-89
Quality Control									
160		0.00							
160	Large Fab					<u>4</u>	<u>16</u>	<u>16-11-9</u>	
Large Fab	Memo	0.59							
Large Fab	1-Weld end caps as per Dwg d3562 & QSI 004. Inspect for foreign objects as per QSI 024. A/RAluminum Rod 3134826 2-Grind end cap welds flush as per Dwg D3562								
170	QC10- Inspect visual per QSI004- ground welds	0.00							
170						<u>4</u>			DAS 38 9-89
QC	Memo	0.00							
Quality Control									

NOV 09 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

July 25, 2016 1:50:19 PM

Page 4

NOV 09 2016

x4

2016/11/10
BEB

PAINT AS PER QSI 005
DRAB GREEN
BATCH 135971

DAS
41
9-89

16-11-10

July 25, 2016 1:50:19 PM

1 49391

Page 5

N900040100

Setup Start *NS1*

Stop *NS2*

4

Cust Item ID:

Start Date: 9/22/2016 **Start Qty:** 4.00

Required Date: 9/30/2016 **Req'd Qty:** 4.00

4

Customer:

Reference:

Approvals: **Process Plan:** **Date:** **Tooling:** **Date:**

Run Start *NR1*

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop *NR2*

Accept Qty	Reject Qty	Reject Number	Insp. Stamp

QC14- Inspect Spray Paint

0.00

202

QC

Memo

0.00

Quality Control

210

Wing Walk as per dwg QSI005 4.4 Batch M135 819 0.00

0.00

210

HandFinish

Memo

0.21

Hand Finishing

220

QC3- Inspect Part Finish

0.00

220

OC

Memo

0.01

Quality Control

Work Order ID 149391

July 25, 2016 1:50:19 PM

149391

Page 6

Item ID: D3562-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Step Weldment
Start Date: 9/22/2016 Start Qty: 4.00 ***4*** Cust Item ID:
Required Date: 9/30/2016 Req'd Qty: 4.00 ***4*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
230	Identify as per dwg & Stock Location: <u>W/O</u>	0.00							
230									
Packaging	Memo	0.01				<u>4X</u>			<u>16/11/15</u>
Packaging									DAS 36 9-89
240	QC21- Final Inspection - Work Order Release	0.00							
240									
QC	Memo	0.07							DAS 21 9-89
Quality Control									NOV 15 2016

16-11-15

Picklist Print

July 22, 2016 3:10:24 PM

Page 1

Work Order ID: 149391

149391

Parent Item: D3562-041

D3562-041

Parent Item Name: Step Weldment

Start Date: 9/22/2016

Required Date: 9/30/2016

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:A New Issue 06-11-09 JLM
 IPP rev B ECN 987 07.10.09 EC verified by: DD
 IPP Rev:C ECN1048 07-12-18 DD verified by:ec
 IPP Rev:D 08-07-28 add chemical conversion coat DD verf:EC IPP REV:E
 13.06.03 PER DWG REV.F DD VERF:JLM IPP REV:F 16.06.23
 AS PER DWG REV.G DD VERF:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS20600-AD4W4		Purchased		No			Each	1,544.000		128			DAS 24 9-89
MS20600-AD4W4													
Rivets													

**** 4135442 → 128x**

Location	Loc Qty	Loc Code
CCK005	1270	
M133990	770	
M134955	500	
LG	74	
M133694	74	
ST308	140	
M133990	140	
WA003	60	
M133990	60	

NOV 09 2016

D2622-120C

Manufactured No

100 Each 117.7360 1 4

D2622-120C

Step Extrusion

Location	Loc Qty	Loc Code
WA003	97.736	
130161	0.236	
141814	97.5	
WA004	20	
140539	20	

**** 4135442 → 128x**
B150070
4 S 8-11-2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐	OTHER :							
Misidentified ☐	Past Due ☐								

Picklist Print

July 22, 2016 3:10:24 PM

Page 2

Work Order ID: 149391

149391

Parent Item: D3562-041

D3562-041

Parent Item Name: Step Weldment

Start Date: 9/22/2016

Required Date: 9/30/2016

Start Qty: 4.00

Required Qty: 4.00

D2734

Manufactured No

140 Each 55.0000 2 8

D2734

Step End Plate

**

NOV 09 2016

DAS
24
9-89

Location

Loc Qty

Loc Code

WA003

55

B151475 → (8x)

145802

55

D3560-041

Manufactured No

140 Each 1.0000 1 4

D3560-041

Arm Weldment

**

B149376 → 4x

DAS
43
9-89

NOV 08 201

Location

Loc Qty

Loc Code

WA003

1

124288

1

D3560-043

Manufactured No

140 Each 0.0000 1 4

D3560-043

Arm Weldment

**

B149341 → 5x

DAS
43
9-89

NOV 08 201

B148356 → 1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE


QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date: _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By		
							Lead hand / Supervisor Approval Verification		
							QC / QA Coordinator Approval		

Root Cause				FAULT CATEGORY			
Environment ☐	Design ☐	Doc/Data ☐	Equip/Tooling ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Handling/Pre ☐	Material ☐	Internal Transport ☐	Tribal Knowledge ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
LOA ☐	Substation ☐	Past Expiry Date ☐	Misidentified ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
				Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
				Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
				Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
				Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
				Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
				Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
				Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
				OTHER : _____			

ITEM	QTY -041	P/N	DESCRIPTION
	X	D3562-041	LH STEP ASSEMBLY
1	1	D3560-041	ARM WELDMENT
2	1	D3560-043	ARM WELDMENT
3	1	D3562-1	STEP ASSEMBLY
4	32	MS20600AD4W4	RIVET, BLIND




RELEASED

2016 JUN 22
ECN 14-66

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH:
 - i) POWDER COAT ASSEMBLY:
 - GLOSS WHITE (4.3.5.1) OR
 - GREY SANDETEX (4.3.5.6) OR
 - BLACK SANDETEX (4.3.5.7) OR
 - GREEN SANDETEX (4.3.5.8) PER DART QSI 005 4.3
 - ii) BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 8.80 lbs
- 8) INSTALL ARM WELDMENTS WITH A LAYER OF SCOTCH-WELD DP460 BETWEEN THE ARM WELDMENT AND STEP EXTRUSION. FILL ANY TOOLING HOLES WITH SCOTCH-WELD DP460. CLEAN OFF EXCESS BEFORE POWDER COATING.
- 9) TRANSFER DRILL #30 DEBURR & TOUCH UP HOLES WITH CHEMICAL CONVERSION COAT BEFORE RIVETING



D3562-041 LH STEP ASSEMBLY

DESIGN	CP	DATE	16.04.21
DRAWN	MB	REV. G	
CHECKED	ML	DRAWING NO.	D3562
MFG. APPR.	DD	TITLE	STEP ASSEMBLY
APPROVED	WM	SCALE	NTS
DE APPR.	DS	DATE	16.04.21


DART AEROSPACE LTD
HAWKESBURY, ONTARIO, CANADA

REVISIONS:
REV. G
SHEET 1 OF 3

DATE: 16.04.21


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

ITEM	QTY -042	P/N	DESCRIPTION
	X	D3562-042	RH STEP WELDMENT
1	1	D3560-042	ARM WELDMENT
2	1	D3560-044	ARM WELDMENT
3	1	D3562-1	STEP ASSEMBLY
4	32	MS20600AD4W4	RIVET, BLIND



NOTES:

- 1) MATERIAL: N/A
- 2) FINISH:
 - i) POWDER COAT ASSEMBLY:
 - GLOSS WHITE (4.3.5.1) OR
 - GREY SANDETEX (4.3.5.6) OR
 - BLACK SANDETEX (4.3.5.7) OR
 - GREEN SANDETEX (4.3.5.8) PER DART QSI 005 4.3
 - ii) BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 8.80 lbs
- 8) INSTALL ARM WELDMENTS WITH A LAYER OF SCOTCH-WELD DP460 BETWEEN THE ARM WELDMENT AND STEP EXTRUSION. FILL ANY TOOLING HOLES WITH SCOTCH-WELD DP460. CLEAN OFF EXCESS BEFORE POWDER COATING.
- 9) TRANSFER DRILL #30 DEBURR & TOUCH UP HOLES WITH CHEMICAL CONVERSION COAT BEFORE RIVETING



D3562-042 RH STEP ASSEMBLY


RELEASED

2016 JUN 22 *q*


APPROVED

DESIGN	CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	MB		
CHECKED	ML	DRAWING NO.	REV. G
MFG. APPR.	DD	D3562	SHEET 2 OF 3
APPROVED	WM	TITLE	SCALE
DE APPR.	DS	STEP ASSEMBLY	NTS
DATE	16.04.21	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

ITEM	QTY -1	P/N	DESCRIPTION
	X	D3562-1	STEP ASSEMBLY
1	A/R	D2622-XXX	STEP EXTRUSION
2	2	D2734	END PLATE



D3562-1 STEP ASSEMBLY



DETAIL A D6-2
TYP BOTH ENDS
SCALE 1.5X

NOTES:

- 1) MATERIAL: MAKE FROM D2622 EXTRUSION
- 2) FINISH: CHEMICAL CONVERSION COAT STEP EXTRUSION
PER DART QSI 005 4.1 BEFORE ASSEMBLY
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: 6.68 lbs
- 8) WELDING: ALL WELDS SHALL BE 100% VISUALLY INSPECTED
BY A QUALIFIED INSPECTOR PER DART QSI 004

RELEASED

2016 JUN 22 *q*

APPROVED

DESIGN	CP	DART AEROSPACE LTD	
DRAWN	MB	HAWKESBURY, ONTARIO, CANADA	
CHECKED	ML	DRAWING NO.	REV. G
MFG. APPR.	DD	D3562	SHEET 3 OF 3
APPROVED	WM	TITLE	SCALE
DE APPR.	DS	STEP ASSEMBLY	NTS
DATE	16.04.21	COPYRIGHT © 2006 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	